

# PRODEMAND

YMMS:  Toyota 4Runner   
Engine: 3.0L Eng  
VIN:

Feb 16, 2022  
License:  
Odometer:

## 24

---

Possible faulty air temp sensor (in VAF sensor) or sensor circuit. Will not set code if sensor out of Range (shifted) only.

If sensor circuit is open or shorted, ECM uses internally fixed voltage (fail-safe mode) to keep Engine running & may mask condition.

Check VAF sensor connector & pins for tightness.

Run test.

Tip.

Check for VAF wire harness damage due to misrouting or collision damage on VAF side of vehicle. Look for evidence of body repair work.

If damage suspected, peel wire harness cover back & inspect for wire damage or poor repair connections.

Reprinted Under License from Toyota Motor Sales, U.S.A., Inc., License Agreement TMS1002