

<b>Vehicle » Technical Service Bulletins » All Technical Service Bulletins</b>
--

<b>Number</b>	<b>Date ▲</b>	<b>Title</b>
<a href="#">LI82-85 P-063619</a>	<a href="#">10/06/2016</a>	<a href="#">Comand Online Live Traffic Free Browsing Inoperative</a>
<a href="#">LI91-10 P-054143</a>	<a href="#">10/03/2016</a>	<a href="#">Electric Seat Fore/Aft Adjustment Nonfunctional</a>
<a href="#">LI82-85 P-064765</a>	<a href="#">09/22/2016</a>	<a href="#">Garmin: Traffic Info. Service and or Voice Control Inoperative</a>
<a href="#">LI91-10 P-064912</a>	<a href="#">09/21/2016</a>	<a href="#">BR190 - Play IN Seat Surface (Code 555. AMG Performance Seats)</a>
<a href="#">LI80-45 P-064913</a>	<a href="#">09/20/2016</a>	<a href="#">Power Windows Sliding Roof or Vario Roof/Soft Top Inoperative</a>
<a href="#">LI80-61 P-060558</a>	<a href="#">09/13/2016</a>	<a href="#">Opening Via Radio Remote Control or Keyless/Keyless Start Inop</a>
<a href="#">LI82-85 P-064765</a>	<a href="#">08/26/2016</a>	<a href="#">Garmin Map Pilot Traffic Info and Voice Control Inop</a>
<a href="#">LI82-10 P-064766</a>	<a href="#">08/26/2016</a>	<a href="#">Headlamps Fogged</a>
<a href="#">LI32-22 P-048108</a>	<a href="#">08/17/2016</a>	<a href="#">Grinding/Scraping Noise From Front Axle Area Normal Driving</a>
<a href="#">LI35-30 P-058566</a>	<a href="#">08/17/2016</a>	<a href="#">Throttle Lift Off Clunking Noise From Side Shaft</a>
<a href="#">LI82-85 P-058185</a>	<a href="#">08/16/2016</a>	<a href="#">Central Display Intermittently Displays Antitheft Protection</a>
<a href="#">LI54-10 P-064674</a>	<a href="#">08/12/2016</a>	<a href="#">Engine Does Not Start/Selector Lever Sticks IN P</a>
<a href="#">LI46-20 P-064605</a>	<a href="#">08/01/2016</a>	<a href="#">Play in Steering About Center Position</a>
<a href="#">LI82-60 P-064266</a>	<a href="#">07/29/2016</a>	<a href="#">Audio 20 NTG5 1: Unit Switches Itself Off and On Again</a>
<a href="#">LI91-10 P-064557</a>	<a href="#">07/22/2016</a>	<a href="#">Reset Function of Backrest Adjustment</a>
<a href="#">LI82-61 P-063753</a>	<a href="#">07/22/2016</a>	<a href="#">Becker Map Pilot GEN3: Message Internal Battery Missing/Faulty</a>
<a href="#">LI82-85 P-064311</a>	<a href="#">06/17/2016</a>	<a href="#">Garmin Map Pilot: General Information in the Event of Complaint</a>
<a href="#">LI82-85 P-064225</a>	<a href="#">06/13/2016</a>	<a href="#">Garmin Map Pilot: Notes On Voice Input</a>
<a href="#">LI88-00 P-063728</a>	<a href="#">04/01/2016</a>	<a href="#">Body - License Plate Adapter Mounting Screws</a>
<a href="#">LI80-35 P-063677</a>	<a href="#">03/19/2016</a>	<a href="#">Keyless Entry - Battery in Transmitter Key Discharged</a>
<a href="#">LI82-10 P-063239</a>	<a href="#">02/23/2016</a>	<a href="#">Lighting - Head Lamp Fogging or Drops of Water</a>
<a href="#">LI82-10 P-063240</a>	<a href="#">02/23/2016</a>	<a href="#">Lighting - Head Lamp Fogging or Water Drops</a>
<a href="#">LI91-10 P-063385</a>	<a href="#">02/22/2016</a>	<a href="#">Restraints - Noise From Seats Passenger and Drivers</a>
<a href="#">LI91-10 P-063393</a>	<a href="#">02/22/2016</a>	<a href="#">Body - Seat Covers Are Splitting</a>
<a href="#">LI82-85 P-062889</a>	<a href="#">02/02/2016</a>	<a href="#">Collision Avoidance - Rear Camera Text Displays in 2 Languages</a>
<a href="#">LI82-85 P-063081</a>	<a href="#">02/02/2016</a>	<a href="#">Infotainment - Deactivation of Selected Mercedes Benz Apps</a>
<a href="#">LI42-10 P 063153</a>	<a href="#">01/21/2016</a>	<a href="#">Brakes - Juddering or Shuddering Felt in Rear Axle</a>
<a href="#">LI42-10 P 063154</a>	<a href="#">01/21/2016</a>	<a href="#">Brakes - Shuddering or Juddering From Front Axle</a>
<a href="#">LI42-10 P 063155</a>	<a href="#">01/21/2016</a>	<a href="#">Brakes - Juddering or Shuddering From Front Axle</a>
<a href="#">LI42-10 P-063156</a>	<a href="#">01/21/2016</a>	<a href="#">Brakes - Juddering or Shuddering Felt From Rear Brakes</a>
<a href="#">LI42-10 P-063157</a>	<a href="#">01/21/2016</a>	<a href="#">Brakes - Juddering or Shuddering Felt From Rear Brakes</a>
<a href="#">LI91-30 P-062634</a>	<a href="#">11/18/2015</a>	<a href="#">Restraints - Seat Heater Failure</a>
<a href="#">LI91-16 P-062217</a>	<a href="#">11/11/2015</a>	<a href="#">Restraints - Headrest Is Down and Will Not Adjust</a>
<a href="#">LI68-20 P-062424</a>	<a href="#">11/11/2015</a>	<a href="#">Stowage Compart. in Center Console Makes Noises Rough Terrain</a>
<a href="#">LI82-95 P-062403</a>	<a href="#">10/15/2015</a>	<a href="#">MBRACE(R) - Please Press I Button or Call to Activate</a>
<a href="#">LI54-10 P-062091</a>	<a href="#">08/21/2015</a>	<a href="#">Electrical - DTC C200200 Over Voltage Stored In ESP Control</a>
<a href="#">LI54-30 P-061864</a>	<a href="#">07/17/2015</a>	<a href="#">Instruments - Instrument Control Module Update</a>
<a href="#">LI82-85 P-061863</a>	<a href="#">07/17/2015</a>	<a href="#">Infotainment - Display Turns Off When Controller is Used</a>
<a href="#">LI42-10 P-061801</a>	<a href="#">07/06/2015</a>	<a href="#">Brakes - Vibration and Noise From Front or Rear Axles</a>
<a href="#">S-60 00-23</a>	<a href="#">07/06/2015</a>	<a href="#">Body - Two Component Epoxy Body Filler</a>
<a href="#">LI82-10 P-061580</a>	<a href="#">06/24/2015</a>	<a href="#">Lighting - Residue Inside Headlamp Lens</a>
<a href="#">LI82-85 P-061613</a>	<a href="#">06/10/2015</a>	<a href="#">Infotainment - Facebook(R) App. Cannot be Opened</a>
<a href="#">LI82-95 P-061544</a>	<a href="#">05/29/2015</a>	<a href="#">Infotainment - Unable to Log on Facebook(R)/App Doesn't Show</a>
<a href="#">LI82-85 P-061464</a>	<a href="#">05/18/2015</a>	<a href="#">Navigation - Download Manager(R) Displays SD Card Not Writable</a>
<a href="#">LI82-61 P-061420</a>	<a href="#">05/11/2015</a>	<a href="#">Navigation - Various Messages/BECKER(R) Logo for 2 Minutes</a>

<a href="#">S-98_00-32</a>	<a href="#">04/15/2015</a>	<a href="#">Body - Paint Drying Information</a>
<a href="#">S-27_30-127</a>	<a href="#">03/26/2015</a>	<a href="#">AT - 722.9 Transmission Seal Change</a>
<a href="#">LI27-00_P-060903</a>	<a href="#">02/27/2015</a>	<a href="#">AT - Shift Enhancements for Poor Shift Quality</a>
<a href="#">LI83-10_P-060852</a>	<a href="#">02/17/2015</a>	<a href="#">A/C - Blower Will Not Function, DTC B112F87</a>
<a href="#">S-15_10-74</a>	<a href="#">02/09/2015</a>	<a href="#">Ignition System - Spark Plug Connector Grease Information</a>
<a href="#">S-98_00-13V</a>	<a href="#">02/05/2015</a>	<a href="#">Body - Approved Refinishing Products</a>
<a href="#">S-80_61-63</a>	<a href="#">01/12/2015</a>	<a href="#">Keyless Entry, Keyless Start - Smart Key Functions</a>
<a href="#">LI91-10_P-060560</a>	<a href="#">01/07/2015</a>	<a href="#">Restraints - Front Seat Belt Rubs Seat and Makes Creak Noises</a>
<a href="#">LI54-10_P-060515</a>	<a href="#">12/29/2014</a>	<a href="#">Starting/Charging - Battery Service Required ON Fault B21DF71</a>
<a href="#">LI83-10_P-060403</a>	<a href="#">12/11/2014</a>	<a href="#">AC - Noise From Rear Blower Motor</a>
<a href="#">S-42_10-123A</a>	<a href="#">12/11/2014</a>	<a href="#">Brakes/Wheels - Brake Disc Installation Information</a>
<a href="#">LI91-29_P-059833</a>	<a href="#">11/19/2014</a>	<a href="#">Memory Positioning - Seat/Steering Wheel Will Not Adjust</a>
<a href="#">LI27-00_P-060097</a>	<a href="#">10/28/2014</a>	<a href="#">AT - Fault Code P089300, Limp In Mode</a>
<a href="#">LI27-55_P-060088</a>	<a href="#">10/24/2014</a>	<a href="#">AT - Procedure For Slight Oil Traces On AT</a>
<a href="#">S-42_10-125</a>	<a href="#">10/20/2014</a>	<a href="#">Brakes - Brake Caliper Service Information</a>
<a href="#">LI82-70_p-060004</a>	<a href="#">10/15/2014</a>	<a href="#">Cell Phone - I Phone IOS 8 Upgrade</a>
<a href="#">LI82-85_P-060002</a>	<a href="#">10/15/2014</a>	<a href="#">Cell Phone - Digital Drive Style App Does Not Auto Launch</a>
<a href="#">LI82-70_P-060004</a>	<a href="#">10/15/2014</a>	<a href="#">Cell Phone - Various Complaints After Software Update to IOS8</a>
<a href="#">LI54-10_P-059875</a>	<a href="#">09/25/2014</a>	<a href="#">Charging System - Taking Longer Than Expected to Charge Vehicle</a>
<a href="#">P-72_00-116A</a>	<a href="#">08/06/2014</a>	<a href="#">Body - Modified Door Shells</a>
<a href="#">P-72_00-117</a>	<a href="#">08/01/2014</a>	<a href="#">Body - Cutouts in Door Shells</a>
<a href="#">LI91-10_P-0501614</a>	<a href="#">04/24/2014</a>	<a href="#">Interior - Front Seat Stowage Compartment Doesn't Lock Properly</a>
<a href="#">S-67_10-30</a>	<a href="#">04/11/2014</a>	<a href="#">Windows/Glass - Windshield Bonding System Change</a>
<a href="#">LI82-85_P-058859</a>	<a href="#">04/09/2014</a>	<a href="#">Infotainment - Drive Kit Plus: Car-to-X Function Issues</a>
<a href="#">LI82-85_P-0510463</a>	<a href="#">04/09/2014</a>	<a href="#">COMAND(R)- No Reversing Camera Image, Next/Previous Track</a>
<a href="#">P-88_40-91A</a>	<a href="#">04/01/2014</a>	<a href="#">Body/Electrical - Permanently Illuminated Star Installation</a>
<a href="#">LI88-50_P-0537683</a>	<a href="#">03/25/2014</a>	<a href="#">Body- Rear/Roof Spoiler Protrudes at the Sides or is Misaligned</a>
<a href="#">LI82-85_P-0536005</a>	<a href="#">02/26/2014</a>	<a href="#">Infotainment - Various Erratic COMAND(R) Faults</a>
<a href="#">LI30-30_P-0571392</a>	<a href="#">02/25/2014</a>	<a href="#">Collision Avoidance - Warning Without Obvious Cause</a>
<a href="#">LI46-15_P-058505</a>	<a href="#">02/25/2014</a>	<a href="#">Interior - Creaking Noise When Adjusting Steering Column</a>
<a href="#">LI54-71_P-0564772</a>	<a href="#">02/25/2014</a>	<a href="#">Collision Avoidance- Blind Spot Assist Inoperative</a>
<a href="#">LI83-00_P-0525104</a>	<a href="#">02/20/2014</a>	<a href="#">Interior - Water in the LH/RH Front Seat Control Unit Tray</a>
<a href="#">S-00_01-104</a>	<a href="#">02/19/2014</a>	<a href="#">Infotainment - Content and Application of Data Mediums</a>
<a href="#">LI27-50_P-0497103</a>	<a href="#">02/19/2014</a>	<a href="#">AT - Limp-home Mode, Gearshifts No Longer Possible, DTC's</a>
<a href="#">LI91-10_P-0498943</a>	<a href="#">01/23/2014</a>	<a href="#">Interior - Noise or Play at Seat Adjuster</a>
<a href="#">LI46-35_P-057867</a>	<a href="#">01/06/2014</a>	<a href="#">Steering/Suspension - Scraping/Squeaking Noises When Steering</a>
<a href="#">LI82-61_P-058186</a>	<a href="#">12/23/2013</a>	<a href="#">Navigation - GPS Inoperative/Navigation Display Freezes</a>
<a href="#">LI46-35_P-0554363</a>	<a href="#">12/20/2013</a>	<a href="#">Steering - Red 'Power Steering Malfunction' Displayed</a>
<a href="#">LI46-35_P-0554853</a>	<a href="#">12/20/2013</a>	<a href="#">Steering/Susp. - No Start or Various Fault Messages after Start</a>
<a href="#">LI82-10_P-0517694</a>	<a href="#">12/20/2013</a>	<a href="#">Lighting - Headlamp Unit Fogged/Droplets Forming</a>
<a href="#">LI91-10_P-057914</a>	<a href="#">12/20/2013</a>	<a href="#">Interior - Noises in Area of Front Seat Backrests</a>
<a href="#">LI80-61_P-057752</a>	<a href="#">11/18/2013</a>	<a href="#">Keyless Start System - Keyless-Go(R) Completely Inoperative</a>
<a href="#">S-54_65-261</a>	<a href="#">11/08/2013</a>	<a href="#">Collision Avoidance - Painted PARKTRONIC(R) Sensors Available</a>
<a href="#">S-00_40-89D</a>	<a href="#">11/06/2013</a>	<a href="#">AT - Operating Fluid Specification Changes</a>
<a href="#">LI32-22_P-0575692</a>	<a href="#">11/05/2013</a>	<a href="#">Steering/Suspension - Suspension Compressor Inop./Faulty Fuse</a>
<a href="#">2013110002</a>	<a href="#">11/01/2013</a>	<a href="#">Campaign- Update Fuel System Control Module Software</a>
<a href="#">LI54-21_P-057404</a>	<a href="#">10/31/2013</a>	<a href="#">Instruments - Image Interference in Night View System</a>
<a href="#">S-42_10-119</a>	<a href="#">10/29/2013</a>	<a href="#">Brakes - Fabrication of Brake Lines</a>
<a href="#">LI32-25_P-0511233</a>	<a href="#">10/29/2013</a>	<a href="#">Suspension - Noises From Front Axle Suspension Struts</a>
<a href="#">LI82-60_P-0574061</a>	<a href="#">10/28/2013</a>	<a href="#">Infotainment- 'Theft Protection Active-Please Visit MB Workshop</a>
<a href="#">LI82-85_P-0571912</a>	<a href="#">10/28/2013</a>	<a href="#">Infotainment - Mute Function Not Active After a Restart</a>

<a href="#">LI82-10 P-0534393</a>	<a href="#">09/13/2013</a>	<a href="#">Lighting - 'High Beam Assist Inoperative' Message Appears</a>
<a href="#">LI82-85 P-057192</a>	<a href="#">09/09/2013</a>	<a href="#">Infotainment - Intermittently NO Audio Output after Engine Star</a>
<a href="#">LI82-62 P-050505</a>	<a href="#">09/06/2013</a>	<a href="#">Navigation Sys. - Poor Reception/Location 'No Service' Display</a>
<a href="#">LI82-85 P-057016</a>	<a href="#">09/06/2013</a>	<a href="#">Infotainment - Drive Kit Plus Stability Improvements</a>
<a href="#">LI42-15 P-057107</a>	<a href="#">09/03/2013</a>	<a href="#">Brakes - Clatter from Front Axle/Brakes on Rough Terrain</a>
<a href="#">LI82-85 P-0556953</a>	<a href="#">08/28/2013</a>	<a href="#">Infotainment - Doesn't Start, Can't Be Operated, Dark Display</a>
<a href="#">LI88-20 P-056908</a>	<a href="#">08/26/2013</a>	<a href="#">Body - Wind Noises at Windshield Between 90 and 120 km/h</a>
<a href="#">LI82-60 P-056890</a>	<a href="#">08/21/2013</a>	<a href="#">Audio System - No/Poor Radio Reception in AM Frequency Range</a>
<a href="#">LI82-70 P-056963</a>	<a href="#">08/21/2013</a>	<a href="#">Infotainment - Cell Phone Connectivity via Bluetooth(R) Concern</a>
<a href="#">LI91-25 P-0515992</a>	<a href="#">08/12/2013</a>	<a href="#">Interior - Dynamic Seat Function Of Front Seats Inop./Noises</a>
<a href="#">LI91-30 P-0546373</a>	<a href="#">08/12/2013</a>	<a href="#">Interior - Lump Visible or Felt Under Seat Cushion Cover</a>
<a href="#">LI82-61 P-0560442</a>	<a href="#">08/08/2013</a>	<a href="#">Navigation - Becker(R)MAP PILOT House Address Numbers Not Found</a>
<a href="#">LI82-61 P-0563882</a>	<a href="#">08/08/2013</a>	<a href="#">Navigation System - Navigation Announcements Inoperative</a>
<a href="#">LI82-95 P-0566552</a>	<a href="#">07/23/2013</a>	<a href="#">Instruments - Battery Drain Bus Keepawake Detected, Low Battery</a>
<a href="#">S-40 10-79</a>	<a href="#">07/23/2013</a>	<a href="#">Wheels/Tires - Cosmetic Processing of Light Alloy Wheels</a>
<a href="#">LI68-10 P-056727</a>	<a href="#">07/16/2013</a>	<a href="#">Interior - Glove Box Squeaks/Rattles at Top Left Mounting</a>
<a href="#">LI91-10 P-0541433</a>	<a href="#">07/10/2013</a>	<a href="#">Interior - Power Seat Fore/Aft Adjustment Inoperative</a>
<a href="#">S-60 00-22</a>	<a href="#">07/02/2013</a>	<a href="#">Body - Handling Lead-Free Filling Solder</a>
<a href="#">2013050005</a>	<a href="#">06/28/2013</a>	<a href="#">Campaign - Automatic Transmission Replacement</a>
<a href="#">S-82 61-702</a>	<a href="#">06/26/2013</a>	<a href="#">Navigation - Becker(R) MAP PILOT Module Information</a>
<a href="#">LI62-25 P-056043</a>	<a href="#">06/05/2013</a>	<a href="#">Body - Engine Compartment Soundproofing Deformation</a>
<a href="#">S-32 25-82C</a>	<a href="#">06/04/2013</a>	<a href="#">Suspension - Strut/Shock Absorber Replacement Guidelines</a>
<a href="#">LI32-22 P-0485973</a>	<a href="#">06/04/2013</a>	<a href="#">Suspension - Vehicle Drops At Rear Axle After Sitting</a>
<a href="#">S-54 10-243B</a>	<a href="#">05/30/2013</a>	<a href="#">Electrical - Battery Test &amp;#38: Inspection Information</a>
<a href="#">S-91 40-200</a>	<a href="#">05/29/2013</a>	<a href="#">Restraint- Reversible Emergency Tensioning Retractor Adaptation</a>
<a href="#">LI20-40 P-0537182</a>	<a href="#">05/23/2013</a>	<a href="#">Cooling System - Coolant Fan ON With Ignition OFF</a>
<a href="#">LI03-10 P-0522863</a>	<a href="#">05/23/2013</a>	<a href="#">Engine - Knocking Noise From Crank Assembly</a>
<a href="#">2013020002B</a>	<a href="#">05/17/2013</a>	<a href="#">Recall - Replace Fuel Filter</a>
<a href="#">LI72-00 P-055920</a>	<a href="#">05/01/2013</a>	<a href="#">Body - Outside Door Handle Inoperative After Operation</a>
<a href="#">LI46-20 P-0498522</a>	<a href="#">04/24/2013</a>	<a href="#">Steering - Honk Or Squeak When Steering In Both Directions</a>
<a href="#">LI82-61 P-055955</a>	<a href="#">04/24/2013</a>	<a href="#">Navigation - Becker(R) MAP PILOT Freezes/Slow/Delayed Response</a>
<a href="#">LI82-61 P-0559542</a>	<a href="#">04/24/2013</a>	<a href="#">Navigation - Becker(R)MAP PILOT 'No Navigation Module Connected</a>
<a href="#">LI33-30 P-055908</a>	<a href="#">04/12/2013</a>	<a href="#">Drivetrain - Noises at Full Lock From Front Axle Area</a>
<a href="#">S-80 61-61A</a>	<a href="#">04/04/2013</a>	<a href="#">Anti Theft System - 'Replace Key Battery' Message Displayed</a>
<a href="#">LI82-85 P-055696</a>	<a href="#">03/26/2013</a>	<a href="#">COMAND(R) - No Sound, 'Device Unavailable' Displayed</a>
<a href="#">LI68-30 P-0539622</a>	<a href="#">03/14/2013</a>	<a href="#">Interior - UV Radiation Fading Of Wood Trim</a>
<a href="#">LI72-00 P-055756</a>	<a href="#">03/14/2013</a>	<a href="#">Body - Front/Rear Door Seal Loose</a>
<a href="#">LI82-70 P-0542264</a>	<a href="#">03/01/2013</a>	<a href="#">Cell Phone/Voice Control - Interference/Background Noise</a>
<a href="#">LI82-85 P-0547162</a>	<a href="#">02/08/2013</a>	<a href="#">COMAND(R) - NTG 4, Intermittent No audio, 'Device Unavailable'</a>
<a href="#">S-14 00-31</a>	<a href="#">02/01/2013</a>	<a href="#">Emissions - I/m Dynamometer Emissions Testing</a>
<a href="#">C1A140101</a>	<a href="#">02/01/2013</a>	<a href="#">Campaign - Verizon(R) Telematics i-button Call</a>
<a href="#">LI77-00 P-055046</a>	<a href="#">01/16/2013</a>	<a href="#">Body - Moisture In Area of A-Pillar Trim/Headliner</a>
<a href="#">S-98 00-31</a>	<a href="#">01/09/2013</a>	<a href="#">Body - Cleaning Tin-Plated Surfaces</a>
<a href="#">LI72-40 P-0550452</a>	<a href="#">01/07/2013</a>	<a href="#">Body/Electrical - Various Door Control Function Failures</a>
<a href="#">LI68-50 P-053634</a>	<a href="#">12/21/2012</a>	<a href="#">Interior - Twin-Rollerblind Malfunction</a>
<a href="#">LI88-70 P-0502282</a>	<a href="#">12/21/2012</a>	<a href="#">Body - Meow/Whistle Noise After Retracting/Extending Mirrors</a>
<a href="#">S-42 15-122</a>	<a href="#">12/13/2012</a>	<a href="#">Brakes - Brake Rotors Treated With Zinc Dust Spray Paint</a>
<a href="#">S-54 50-256</a>	<a href="#">12/10/2012</a>	<a href="#">Instruments - Reset Trip Computer After ECU Software Update</a>

<a href="#">201207002B</a>	<a href="#">11/01/2012</a>	<a href="#">Campaign - Retrofit Camshaft Adj. Solenoid Adapter Wire Harness</a>
<a href="#">S-58 40-161</a>	<a href="#">10/24/2012</a>	<a href="#">Body/Frame - Dedicated Frame Straightener</a>
<a href="#">S-80 61-59</a>	<a href="#">10/22/2012</a>	<a href="#">Keyless System/Instruments - 'Replace Key Battery' Displayed</a>
<a href="#">S-27 00-124</a>	<a href="#">10/03/2012</a>	<a href="#">A/T - 722.9 Additional Adaptation Counter Indicator</a>
<a href="#">S-28 00-12</a>	<a href="#">09/26/2012</a>	<a href="#">A/T - 722.96 Transmission Group 28 Damage Code Changes</a>
<a href="#">S-88 30-88</a>	<a href="#">09/26/2012</a>	<a href="#">Body - License Plate Bracket Installation Precautions</a>
<a href="#">LI91-10 P-0484113</a>	<a href="#">09/21/2012</a>	<a href="#">Interior - Pneumatic 4-Way Lumbar Support Fails</a>
<a href="#">LI27-00 P-0485525</a>	<a href="#">09/17/2012</a>	<a href="#">A/T - 2-3 Upshift Slip During Initial Cold Acceleration</a>
<a href="#">LI82-60 P-054090</a>	<a href="#">09/13/2012</a>	<a href="#">Entertainment Sys. - iPad(R) Rear Integration Plus Noises</a>
<a href="#">LI54-35 P-053444</a>	<a href="#">09/07/2012</a>	<a href="#">Electrical - Horns Too Quiet, Inoperative, Or Has Poor Sound</a>
<a href="#">LI46-10 P-054502</a>	<a href="#">09/06/2012</a>	<a href="#">Steering - Scraping Noises When Steering</a>
<a href="#">LI54-10 P-0540892</a>	<a href="#">09/03/2012</a>	<a href="#">Electrical - Battery Discharged, Vehicle Doesn't Start</a>
<a href="#">S-30 30-67</a>	<a href="#">08/15/2012</a>	<a href="#">Collision Avoidance - Short Range Sensor Replacement Info.</a>
<a href="#">S-83 30-136</a>	<a href="#">08/15/2012</a>	<a href="#">A/C - A/C Sealant</a>
<a href="#">LI27-20 P-051537</a>	<a href="#">08/07/2012</a>	<a href="#">A/T - Hard 1-2 And 2-3 Shifts, Driveability, DTC's</a>
<a href="#">LI54-21 P-053525</a>	<a href="#">07/31/2012</a>	<a href="#">Engine Controls - MIL ON And DTC 2060 Stored</a>
<a href="#">LI91-25 P-051700</a>	<a href="#">07/17/2012</a>	<a href="#">Interior - Massage Function in Multicontour Seat Inoperative</a>
<a href="#">S-54 10-255</a>	<a href="#">07/03/2012</a>	<a href="#">Battery - Battery Charging Information</a>
<a href="#">LI82-85 P-0479912</a>	<a href="#">06/12/2012</a>	<a href="#">Audio/COMAND(R) - Volume In AUX Menu Is Erratic</a>
<a href="#">LI68-50 P-053632</a>	<a href="#">06/07/2012</a>	<a href="#">Body - Stowage Basket Under Rear Shelf Jams</a>
<a href="#">LI27-57 P-0534962</a>	<a href="#">05/22/2012</a>	<a href="#">A/T - ECO Start/Stop Inoperative, DTC P0944 Stored In TCM</a>
<a href="#">LI28-10 P-0519352</a>	<a href="#">05/22/2012</a>	<a href="#">Drivetrain - Oil Leak At Seam Between A/T And Transfer Case</a>
<a href="#">S-80 57-57A</a>	<a href="#">05/17/2012</a>	<a href="#">Keyless Entry/Start - Replacement And Diagnosis Revision</a>
<a href="#">LI83-30 P-0536372</a>	<a href="#">05/01/2012</a>	<a href="#">A/C - Blower Occasionally Inoperative/DTC's Stored</a>
<a href="#">P-91 25-198</a>	<a href="#">05/01/2012</a>	<a href="#">Interior - Active Multicontour Seat Comfort System</a>
<a href="#">S-91 40-198</a>	<a href="#">04/27/2012</a>	<a href="#">Restraints - Seat Belt Buckle Warranty Replacement Information</a>
<a href="#">LI72-10 P-053587</a>	<a href="#">04/19/2012</a>	<a href="#">Body - Rattle On Door Lock Of Left/Right Front Door</a>
<a href="#">LI67-30 P-0506133</a>	<a href="#">04/19/2012</a>	<a href="#">Windows - Front Windows Reverse Direction When Closing</a>
<a href="#">LI88-30 P-053562</a>	<a href="#">04/09/2012</a>	<a href="#">Body - Wheel Well Liners In Engine Compartment Heavily Soiled</a>
<a href="#">S-46 10-72</a>	<a href="#">04/09/2012</a>	<a href="#">Steering - Warranty Policy Regarding Steering Wheels</a>
<a href="#">LI54-10 P-051049</a>	<a href="#">04/05/2012</a>	<a href="#">Electrical - Consumer Shutoff Intermittently Active</a>
<a href="#">LI82-60 P-051747</a>	<a href="#">04/05/2012</a>	<a href="#">COMAND(R) - Music Playback From iPhone(R) Is Not Resumed</a>
<a href="#">LI91-40 P-0471834</a>	<a href="#">04/05/2012</a>	<a href="#">Restraints - Difficult To Pull Seat Belt Out</a>
<a href="#">LI83-00 P-050296</a>	<a href="#">03/26/2012</a>	<a href="#">A/C - DTC 90A207 And Significant Temperature Differences</a>
<a href="#">LI88-20 P-053415</a>	<a href="#">03/20/2012</a>	<a href="#">Body - Rear Bumper Sticks Out In Area Of Rear Lamp</a>
<a href="#">S-83 00-135</a>	<a href="#">03/02/2012</a>	<a href="#">A/C - HVAC - Foam Cleaner Information and Work Procedure</a>
<a href="#">S-54 65-251</a>	<a href="#">02/07/2012</a>	<a href="#">Parking Assist - Parktronic Sensor Return Policy</a>
<a href="#">S-54 65-252</a>	<a href="#">02/07/2012</a>	<a href="#">Parking Assist - Malfunction and Fault Scenarios</a>
<a href="#">S-27 00-123</a>	<a href="#">02/07/2012</a>	<a href="#">A/T - ECU Version - EEPROM Log Retrieval Process</a>
<a href="#">P-91 20-196</a>	<a href="#">01/20/2012</a>	<a href="#">Interior - Integrated Child Seat Lock</a>
<a href="#">S-91 60-195A</a>	<a href="#">01/18/2012</a>	<a href="#">Restraints - Repair And Diag. Of Airbag Wiring Harnesses</a>
<a href="#">S-01 20-32A</a>	<a href="#">01/03/2012</a>	<a href="#">Engine - Cylinder Head Cover Leak Information</a>
<a href="#">S-82 00-701</a>	<a href="#">01/03/2012</a>	<a href="#">Audio/COMAND(R) - Repair Of Wiring Harnesses</a>
<a href="#">P-42 30-118</a>	<a href="#">12/19/2011</a>	<a href="#">Brakes/Traction Control - Handling Multipole Rings</a>
<a href="#">S-40 10-74</a>	<a href="#">11/29/2011</a>	<a href="#">Wheels/Tires - Wheels/Tire Change Information</a>
<a href="#">2011100004</a>	<a href="#">11/01/2011</a>	<a href="#">Campaign - Update Central Gateway Software</a>
<a href="#">S-88 30-87</a>	<a href="#">10/28/2011</a>	<a href="#">Body - License Plate Bracket Omission</a>
<a href="#">S-42 10-117</a>	<a href="#">09/20/2011</a>	<a href="#">Brakes - Brake Lining Instructions</a>
<a href="#">S-47 00-61</a>	<a href="#">09/20/2011</a>	<a href="#">Fuel System - Use Of E10 Fuel</a>
<a href="#">S-54 50-247</a>	<a href="#">09/09/2011</a>	<a href="#">Computer/Controls - Reset Trip Computer After ECU Update</a>
<a href="#">S-32 25-83</a>	<a href="#">09/08/2011</a>	<a href="#">Suspension - Assembly Of Suspension Struts And Shocks</a>

<a href="#"><u>S-46 25-70A</u></a>	<a href="#"><u>08/09/2011</u></a>	<a href="#"><u>Steering - Approved Hydraulic Fluids</u></a>
<a href="#"><u>P-82 85-691A</u></a>	<a href="#"><u>07/26/2011</u></a>	<a href="#"><u>Navigation Sys. - Copy Protection For Hard Disk</u></a>
<a href="#"><u>S-83 00-133</u></a>	<a href="#"><u>07/26/2011</u></a>	<a href="#"><u>A/C System - Update Of Vehicle System Technology Guide</u></a>
<a href="#"><u>S-54 21-244A</u></a>	<a href="#"><u>07/20/2011</u></a>	<a href="#"><u>Engine Control - Engine Control Module (N3/10) Flashing</u></a>
<a href="#"><u>S-54 21-246</u></a>	<a href="#"><u>07/19/2011</u></a>	<a href="#"><u>Computers/Controls - Module Programming Precautions</u></a>
<a href="#"><u>P-88 60-85</u></a>	<a href="#"><u>07/12/2011</u></a>	<a href="#"><u>Body - Fuel Filler Door Customer Error Damage</u></a>
<a href="#"><u>S-27 19-118A</u></a>	<a href="#"><u>07/01/2011</u></a>	<a href="#"><u>AT - Electrohydraulic Control Unit ID &amp;#38; Ordering</u></a>
<a href="#"><u>S-07 04-87</u></a>	<a href="#"><u>07/01/2011</u></a>	<a href="#"><u>Engine Controls - PremAir(R) Sensor R &amp;#38; I Instructions</u></a>
<a href="#"><u>S-07 04-88</u></a>	<a href="#"><u>07/01/2011</u></a>	<a href="#"><u>Cooling System - MIL ON/DTC P2060 Diagnosis</u></a>
<a href="#"><u>LI07-10 P-051967</u></a>	<a href="#"><u>05/31/2011</u></a>	<a href="#"><u>Engine Controls - MIL ON, DTC 2185/2189 Stored</u></a>
<a href="#"><u>S-40 10-72</u></a>	<a href="#"><u>05/19/2011</u></a>	<a href="#"><u>Wheels - Checking Components For Bolted Wheel Connection</u></a>
<a href="#"><u>2011030004A</u></a>	<a href="#"><u>05/03/2011</u></a>	<a href="#"><u>Recall - Check Vibration Damper, Replace If Necessary</u></a>
<a href="#"><u>S-27 00-120A</u></a>	<a href="#"><u>04/29/2011</u></a>	<a href="#"><u>AT - Diag. Verification For Valve Body/Conductor Plate</u></a>
<a href="#"><u>P-68 30-81</u></a>	<a href="#"><u>04/14/2011</u></a>	<a href="#"><u>Interior - Leather Surface Appearance Information</u></a>
<a href="#"><u>LI27-60 P-049270</u></a>	<a href="#"><u>04/04/2011</u></a>	<a href="#"><u>AT - AT 722.9 Switches To Limp-Home Mode</u></a>
<a href="#"><u>NHTSA11V213000</u></a>	<a href="#"><u>03/31/2011</u></a>	<a href="#"><u>Recall 11V213000: Engine Mass Damper Separation</u></a>
<a href="#"><u>S-54 00-238</u></a>	<a href="#"><u>03/23/2011</u></a>	<a href="#"><u>Electrical - Electrostatic Discharge Damage Prevention</u></a>
<a href="#"><u>LI27-60 P-051470</u></a>	<a href="#"><u>03/23/2011</u></a>	<a href="#"><u>AT - Hard 2-3 Upshift Or Slips, No 3rd Gear/DTC's Stored</u></a>
<a href="#"><u>S-82 10-698</u></a>	<a href="#"><u>02/22/2011</u></a>	<a href="#"><u>Lighting - Uprated H7 Bulbs</u></a>
<a href="#"><u>LI68-20 P-050951</u></a>	<a href="#"><u>02/11/2011</u></a>	<a href="#"><u>Interior - Ashtray and or Stowage Compartment Functionality</u></a>
<a href="#"><u>P-54 10-236</u></a>	<a href="#"><u>02/10/2011</u></a>	<a href="#"><u>Electrical - Battery Sensor Data Readout</u></a>
<a href="#"><u>2010120001</u></a>	<a href="#"><u>01/21/2011</u></a>	<a href="#"><u>Campaign - Cylinder Head Replacement</u></a>
<a href="#"><u>P-42 47-115</u></a>	<a href="#"><u>01/18/2011</u></a>	<a href="#"><u>ABS/TCS - ABR Control Unit Programming/Start-Up Info.</u></a>
<a href="#"><u>S-54 21-235</u></a>	<a href="#"><u>12/01/2010</u></a>	<a href="#"><u>Computer/Controls - SAM Control Unit Diagnosis Procedure</u></a>
<a href="#"><u>S-54 21-234A</u></a>	<a href="#"><u>10/26/2010</u></a>	<a href="#"><u>Electrical - Aftermarket Tampering Malfunctions</u></a>
<a href="#"><u>P-42 47-114</u></a>	<a href="#"><u>10/19/2010</u></a>	<a href="#"><u>ABS/TCS - ABR Control Unit Programming Issues</u></a>
<a href="#"><u>P-65 10-06</u></a>	<a href="#"><u>09/08/2010</u></a>	<a href="#"><u>Body - Roof Paneling Information</u></a>
<a href="#"><u>P-77 21-84</u></a>	<a href="#"><u>09/08/2010</u></a>	<a href="#"><u>Body - Panoramic Sliding Roof Information</u></a>
<a href="#"><u>S-80 57-56</u></a>	<a href="#"><u>09/08/2010</u></a>	<a href="#"><u>Audio System - Radio Interruption Information</u></a>
<a href="#"><u>S-00 45-94</u></a>	<a href="#"><u>08/27/2010</u></a>	<a href="#"><u>Chemicals/Lubrication - Multi-Grade Metal Grease Info.</u></a>
<a href="#"><u>LI82-10 P-050139</u></a>	<a href="#"><u>08/18/2010</u></a>	<a href="#"><u>Lighting - Headlamps/Front Fog Lamps Leaking Or Fogged</u></a>
<a href="#"><u>LI91-40 P-0479212</u></a>	<a href="#"><u>08/17/2010</u></a>	<a href="#"><u>Restraints - (PRE-SAFE) Inactive And DTC 530630 Stored</u></a>
<a href="#"><u>S-98 00-28</u></a>	<a href="#"><u>08/01/2010</u></a>	<a href="#"><u>Paint - Clearcoat With Higher Scratch Resistance</u></a>
<a href="#"><u>LI91-18 P-049463</u></a>	<a href="#"><u>04/29/2010</u></a>	<a href="#"><u>Interior - Multicontour Seat Cushion Cover Becomes Detached</u></a>
<a href="#"><u>LI58-40 P-049468</u></a>	<a href="#"><u>04/20/2010</u></a>	<a href="#"><u>Computer/Controls - DAS/XD Add-On 2010-03-08-1397</u></a>
<a href="#"><u>LI40-15 P-047029</u></a>	<a href="#"><u>06/09/2009</u></a>	<a href="#"><u>TPMS - Warranty Repair Information</u></a>