

Connector: **C2DB04A**

**CONNECTOR HOUSING NOT SERVICEABLE**

Description: **Connector-MOST diagnostic**

Location: **Behind Instrument panel trim panel**

Qualifier:


ASSEMBLY

Part No.: **XUD901790**

Colour: **NO COLOUR**

Cavities: **1WY**

Harness: **INSTRUMENT PANEL LHD HARNESS**



**Wire Chart**

CAV	CSA	COL	CCT	DESTN
1	1.0	OG	ALL	C2MT01B
2	1.0	OG	ALL	C2MC02C