

GEICO

GEICO

Request a supplement at partners.geico.com

5260 WESTERN AVE

CHEVY CHASE, MD 20815

Phone: (240) 393-9676

Fax: (877) 303-1091

Claim #: 0443089200101150-01
Workfile ID: 069fb09c

Estimate of Record

Written By: ALEX KING, 4/8/2019 4:50:42 PM

Adjuster: A089

Insured:	Saliou Fall	Owner Policy #:	4263721229	Claim #:	0443089200101150-01
Type of Loss:	Collision	Date of Loss:	03/31/2019 11:44 AM	Days to Repair:	6
Point of Impact:	12 Front	Deductible:	500.00		

Owner (Insured):	Inspection Location:	Appraiser Information:	Repair Facility:
Saliou Fall 16208 Eastham Ct Bowie, MD 20716 (240) 330-5479 Evening	OURISMAN CHEV BOWIE - XD OURISMAN CHEV BOWIE - XD 16610 GOVERNOR BRIDGE RD BOWIE, MD 20716 Non Drive-in (301) 262-7600 Day	alexking@geico.com (240) 393-9676	Ourisman Chev BOWIE 16610 Governor Bridge Rd. BOWIE, MD 20716 (301) 262-7600 Day 200913180 Federal ID dennis.messer@ourismanautomotive.com

VEHICLE

2016 NISS Versa SL w/Continuously Variable Transmission 4D SED 4-1.6L Gasoline Sequential MPI Red

VIN:	3N1CN7APXGL822436	Production Date:		Interior Color:	Gray
License:	1ct5558	Odometer:	64681	Exterior Color:	Red
State:	MD	Condition:			

TRANSMISSION	TRACTION CONTROL	SAFETY	SIGNAL INTEGRATED MIRRORS
AUTOMATIC TRANSMISSION	STABILITY CONTROL	DRIVERS SIDE AIR BAG	TINTED GLASS
DRIVER CONVENIENCE	AIR CONDITIONING	PASSENGER AIR BAG	SEATS
KEYLESS ENTRY	REAR DEFOGGER	FRONT SIDE IMPACT AIR BAGS	CLOTH SEATS
POWER WINDOWS	HANDS FREE DEVICE	HEAD/CURTAIN AIR BAGS	BUCKET SEATS
POWER LOCKS	NAVIGATION SYSTEM	PAINT	RECLINING/LOUNGE SEATS
POWER MIRRORS	RADIO	CLEARCOAT PAINT	REAR END
POWER TRUNK/GATE RELEASE	AM RADIO	FRONT END	BACKUP CAMERA W/ PARKING SENSORS
CRUISE CONTROL	FM RADIO	FOG LAMPS	REAR SPOILER
INTERMITTENT WIPERS	STEREO	POWER STEERING	WHEELS
TILT WHEEL	SEARCH/SEEK	POWER BRAKES	ALUMINUM/ALLOY WHEELS
STEERING WHEEL TOUCH CONTROLS	CD PLAYER	ANTI-LOCK BRAKES (4)	
CONSOLE/STORAGE	AUXILIARY AUDIO CONNECTION	GLASS & MIRRORS	
INSTRUMENT PANEL	SATELLITE RADIO	DUAL MIRRORS	

Estimate of Record

2016 NISS Versa SL w/Continuously Variable Transmission 4D SED 4-1.6L Gasoline Sequential MPI Red

Line	Oper	Description	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER & GRILLE				
2	R&I	R&I bumper cover			1.0	
3	**	Repl A/M RT Bezel w/fog lamps w/chrome	1	51.00	0.1	
4		R&I LT Bezel w/fog lamps w/chrome			0.1	
5	**	Repl A/M Grille w/chrome	1	175.38	0.3	
		NOTE: Grille damage in rt center.				
6	*	R&I Lower molding			<u>Incl.</u>	
7	* <>	Rpr Bumper cover w/chrome molding			<u>2.0</u>	<u>2.2</u>
		NOTE: bumper damage from license plate bracke to beneath headlamp. Includes time to clean and repair missing plastic.				
8	*	Add for Clear Coat				<u>1.0</u>
9	*	Repl Bumper cover clip	5	<u>2.20</u>		
10	**	Repl A/M CAPA Absorber	1	67.00	Incl.	
11	*	Repl LKQ Impact bar +25%	1	318.75	<u>0.4</u>	
		NOTE: Damaged in rt top				
12	**	Repl A/M License bracket	1	30.00	0.2	
13	*	R&I Emblem			<u>Incl.</u>	
14	*	Rpr Hole cover			<u>0.5</u>	0.2
15		Add for Clear Coat				0.1
16	*	R&I Hole cover			<u>Incl.</u>	
17	**	Repl A/M RT Side bracket	1	5.00	0.1	
18		FRONT LAMPS				
19	**	Repl A/M NSF RT Headlamp assy	1	140.00	0.3	
20		Aim headlamps			0.5	
21	**	Repl A/M NSF LT Headlamp assy	1	140.00	0.3	
22		R&I RT Fog lamp assy			0.3	
23		R&I LT Fog lamp assy			0.3	
24		RADIATOR SUPPORT				
25	*	Rpr Upper tie bar sedan			<u>2.0</u>	<u>0.4</u>
		NOTE: Repair for Side brackets which could not be located in CCC. Seperate Pull and Setup for to align rad support properly.				
26		HOOD				
27	*	Align LT Hinge			<u>0.5</u>	
28	*	Align RT Hinge			<u>0.5</u>	
29		FENDER				
30	*	Rpr RT Fender			<u>5.0</u>	<u>1.8</u>
31		Overlap Major Non-Adj. Panel				-0.2
32	*	Add for Clear Coat				<u>0.4</u>
33		MISCELLANEOUS OPERATIONS				
34	#	Repl Flex Additive	1	5.00 T		
35	#	Pre/Post Scan	1		0.5 M	
		NOTE: Check Engine light after accident. CS veh AC not working and complaint of veh overheating.				

Estimate of Record

2016 NISS Versa SL w/Continuously Variable Transmission 4D SED 4-1.6L Gasoline Sequential MPI Red

Scan found codes

P1217 Overheat THERmostat
 P0300- Missfire

Based on codes, check engine light do no appear to be related to loss.

36	#	Rpr	Set up and measure			1.0
			NOTE: Must be set up and measured in ordered to align rad support properly.			
37	#		Rough Pull	1		1.0
38	#	Repl	Restore Corrosion Protection	1	10.00 T	0.2
39	#	Refn	Cover Car			0.2
40	OTHER CHARGES					
41	#		E.P.C.	1	3.00	
SUBTOTALS					947.33	17.1
						6.1

NOTES

Prior Damage Notes:

f bumper has unrelated damage to either side, lt fender damage, lt f door dented and scratches and hps, lt r door scuffs and scratches and hand pocket scratches, rear bumper park damage, rt r door scratches and scratches and hand pocket scratches, rt f door damage to front end and hand pocket scratches, lt fender has preexisting damage toward rear and center.

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			929.33
Body Labor	16.6 hrs @	\$ 44.00 /hr	730.40
Paint Labor	6.1 hrs @	\$ 44.00 /hr	268.40
Mechanical Labor	0.5 hrs @	\$ 85.00 /hr	42.50
Paint Supplies	6.1 hrs @	\$ 28.00 /hr	170.80
Miscellaneous			15.00
Other Charges			3.00
Subtotal			2,159.43
Sales Tax	\$ 1,115.13 @	6.0000 %	66.91
Total Cost of Repairs			2,226.34
Deductible			500.00
Total Adjustments			500.00
Net Cost of Repairs			1,726.34

Estimate of Record

2016 NISS Versa SL w/Continuously Variable Transmission 4D SED 4-1.6L Gasoline Sequential MPI Red

This is not an authorization to repair.

All GEICO customers have the right to have their vehicle repaired in the shop of their choice.

No Supplement will be honored unless authorized by GEICO.

NOTICE: Vehicles constructed of special metals may require the use of specialized welding and bonding equipment. Proper measuring and structural repair systems are required on today's vehicle to accurately accomplish vehicle repairs. Make sure your shop has the proper equipment to repair your vehicle.

ALTERNATE PARTS DISCLAIMER:

IF A QUALITY REPLACEMENT PART (A/M, LKQ, RECOND OR OPT OEM) APPEARS ON THIS ESTIMATE, IT INDICATES THAT THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. GUARANTEES, IF ANY, APPLICABLE TO THESE REPLACEMENT CRASH PARTS ARE PROVIDED BY THE PART MANUFACTURER OR DISTRIBUTOR RATHER THAN BY THE MANUFACTURER OF YOUR VEHICLE.

***IN ADDITION TO ANY SUCH GUARANTEES, GEICO PROVIDES THE FOLLOWING:

****OWNER LIMITED GUARANTEE**** WE GUARANTEE THAT ALL QUALITY REPLACEMENT BODY PARTS (PARTS NOT MANUFACTURED BY THE MANUFACTURER) IDENTIFIED ON YOUR ESTIMATE, ARE FREE OF DEFECTS IN MATERIAL AND WORKMANSHIP AND MEET GENERALLY ACCEPTED INDUSTRY STANDARDS. THIS PARTS AND LABOR GUARANTEE WILL BE IN EFFECT FOR AS LONG AS YOU OWN THE VEHICLE DESCRIBED IN THE ESTIMATE. THIS GUARANTEE COVERS THE COST OF THE PART, LABOR TO INSTALL, AND INCIDENTALS SUCH AS PAINT AND MATERIALS AND IS SPECIFICALLY LIMITED TO THOSE ITEMS. THIS GUARANTEE DOES NOT COVER LOSS OR DAMAGE THAT IS UNRELATED TO DEFECTS IN THE QUALITY REPLACEMENT PARTS. THIS IS NOT TRANSFERABLE. IF ANY QUALITY REPLACEMENT PARTS ARE DEFECTIVE IN EITHER MATERIAL OR WORKMANSHIP, CONTACT YOUR LOCAL GEICO REPRESENTATIVE.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AFTERMARKET CRASH PARTS THAT ARE NOT MANUFACTURED BY THE ORIGINAL MANUFACTURER OF THE VEHICLE OR BY A MANUFACTURER AUTHORIZED BY THE ORIGINAL MANUFACTURER TO USE ITS NAME OR TRADEMARK. THE USE OF CERTAIN AFTERMARKET CRASH PARTS MAY MODIFY THE ORIGINAL MANUFACTURER'S WARRANTY ON THE CRASH PARTS BEING REPLACED. UPON REQUEST OF THE CUSTOMER, THE BODY SHOP SHALL PROVIDE, IF AVAILABLE, A COPY OF ANY WARRANTY FOR AN AFTERMARKET CRASH PART USED.

Estimate of Record

2016 NISS Versa SL w/Continuously Variable Transmission 4D SED 4-1.6L Gasoline Sequential MPI Red

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARF3781, CCC Data Date 4/1/2019, and potentially other third party sources of data; and (b) the parts presented are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2019 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Estimate of Record

2016 NISS Versa SL w/Continuously Variable Transmission 4D SED 4-1.6L Gasoline Sequential MPI Red

ALTERNATE PARTS SUPPLIERS

Line	Supplier	Description	Price
3	KSI Trading Corp.-MD George Caracci 7270 Park Circle Drive, E Hanover MD 21076 (800) 882-0058	#537035D A/M RT Bezel w/fog lamps w/chrome	\$ 51.00
5	Empire Auto Parts, MD Michelle Lo 8870 Greenwood Place Savage MD 20763 (240) 554-1300	#N2463 A/M Grille w/chrome	\$ 175.38
10	KEYSTONE - LINTHICUM, MD 4803 HOLLINS FERRY ROAD Halethorpe MD 21227 (410) 636-4600	#NI1070160C A/M CAPA Absorber Quote: 339393870 Expires: 05/22/19	\$ 67.00
11	LKQ Penn-Mar, Inc 269 River Road York Haven PA 17370 (888) 253-7743	#~179297121 LKQ Impact bar +25% Bumper Bar - Front 4DR,CHA,SV SDN, BAR ONLY,S#\$DZ818 Quote: 339393870 Expires: 05/22/19	\$ 255.00
12	KEYSTONE - LINTHICUM, MD 4803 HOLLINS FERRY ROAD Halethorpe MD 21227 (410) 636-4600	#NI1068126 A/M License bracket Quote: 339393870 Expires: 05/22/19	\$ 30.00
17	KSI Trading Corp.-MD George Caracci 7270 Park Circle Drive, E Hanover MD 21076 (800) 882-0058	#5370469 A/M RT Side bracket	\$ 5.00
19	All Star Auto Lights- PA 1039 S. 13th Street HARRISBURG PA 17104 (734) 710-9460	#3151195RAF A/M NSF RT Headlamp assy Quote: 15521255 Expires: 04/17/19	\$ 140.00
21	All Star Auto Lights- PA 1039 S. 13th Street HARRISBURG PA 17104 (734) 710-9460	#3151195LAF A/M NSF LT Headlamp assy Quote: 15521255 Expires: 04/17/19	\$ 140.00

Estimate of Record

2016 NISS Versa SL w/Continuously Variable Transmission 4D SED 4-1.6L Gasoline Sequential MPI Red